

Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 12/24/2019 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 12/24/2019 19111 Collected By Criterion Laboratories, Inc. Analyzed By Raleigh, Nicolette Sample Analysis Date(s) 12/24/2019

						Flow Rate	Volume	Fibers	Fiber Density	
Sample Number	Sample Type	Location	Start	Stop	Mins	(LPM)	(L)	/Fields	f/mm²	Fiber /cc
193142-01-002-01-01	Pre-Test	Inside Work Area (IWA) - Classroom 208 Containment	07:12	09:15	123	9.93	1,221.39	5.0/100	<7.0	<0.002
193142-01-002-01-02	Pre-Test	IWA - Classroom 208 on W3	07:13	09:16	123	9.93	1,221.39	8.0/100	10.2	0.003
193142-01-002-01-03	Pre-Test	IWA - Classroom 208 on W4	07:13	09:18	125	9.93	1,241.25	6.5/100	8.3	0.003
193142-01-002-01-04	Area Sample	IWA - Classroom 209 Containment on W3	08:58	10:59	121	9.93	1,201.53	9.0/100	11.5	0.004
193142-01-002-01-05	Area Sample	Outside Work Area (OWA) - Classroom 209 by Teachers Desk	08:58	10:59	121	9.93	1,201.53	7.0/100	8.9	0.003
193142-01-002-01-06	Area Sample	IWA - Classroom 208 Containment	09:16	11:20	124	9.93	1,231.32	4.0/100	<7.0	<0.002
193142-01-002-01-07	Area Sample	IWA - Classroom 208 on W3	09:17	11:20	123	9.93	1,221.39	8.5/100	10.8	0.003
193142-01-002-01-08	Area Sample	OWA - Classroom 208 on W4	09:19	11:21	122	9.93	1,211.46	6.0/100	7.6	0.002
193142-01-002-01-09	Field Blank	blank						0.0/100	<7.0	
193142-01-002-01-10	Field Blank	blank						0.0/100	<7.0	

Sample Count 10



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM
Container Bag

**Project** 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Nicolette Raleigh

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

Sample Number	Sample Type	Location	Received Condition	Date	Notes
193142-01-002-01-01	Pre-Test	Inside Work Area (IWA) - Classroom 208 Containment	Good	12/24/2019	Notes
193142-01-002-01-02	Pre-Test	IWA - Classroom 208 on W3	Good	12/24/2019	
193142-01-002-01-03	Pre-Test	IWA - Classroom 208 on W4	Good	12/24/2019	
193142-01-002-01-04	Area Sample	IWA - Classroom 209 Containment on W3	Good	12/24/2019	
193142-01-002-01-05	Area Sample	Outside Work Area (OWA) - Classroom 209 by Teachers Desk	Good	12/24/2019	
193142-01-002-01-06	Area Sample	IWA - Classroom 208 Containment	Good	12/24/2019	
193142-01-002-01-07	Area Sample	IWA - Classroom 208 on W3	Good	12/24/2019	
193142-01-002-01-08	Area Sample	OWA - Classroom 208 on W4	Good	12/24/2019	
193142-01-002-01-09	Field Blank	blank	Good	12/24/2019	
193142-01-002-01-10	Field Blank	blank	Good	12/24/2019	

Sample Count \_\_10\_

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	12/24/2019	07:00	
Send Reports To	School District of Philadelphia	12/24/2019	07:00	
Samples Taken By	Nicolette Raleigh	12/24/2019	07:15	
Received By	Nicolette Raleigh	12/24/2019	11:20	
Analyzed By	Nicolette Raleigh	12/24/2019	11:50	
Transported By	Nicolette Raleigh	12/24/2019	12:00	



Relinquished By

Nicolette Raleigh

12/24/2019 13:00



Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 12/24/2019 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 12/24/2019 Collected By Scally, Paul Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 12/24/2019

						Flow Rate	Volume	Fibers	Fiber Density	
Sample Number	Sample Type	Location	Start	Stop	Mins	(LPM)	(L)	/Fields	f/mm <sup>2</sup>	Fiber /cc
193142-01-002-02-01	Post-Test	Room 208 in tent near hepa	15:15	17:17	122	9.90	1,207.80	1.0/100	<7.0	<0.002
193142-01-002-02-02	Post-Test	Room 208 in tent near risers	15:16	17:19	123	9.80	1,205.40	0.5/100	<7.0	<0.002
193142-01-002-02-03	Area Sample	Gym storage room (s.) at door	16:00	18:00	120	10.00	1,200.00	2.0/100	<7.0	<0.002
193142-01-002-02-04	Area Sample	Gym storage room (n.) at door	16:01	18:02	121	10.00	1,210.00	2.0/100	<7.0	<0.002
193142-01-002-02-05	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-02-06	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count



6

James A. Weltz, CIH, Technical Director

Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

Sample Number	Sample Type	Location	Received Condition	Date	Notes
Sample Number	Sample Type	Location	Condition	Date	140162
193142-01-002-02-01	Post-Test	Room 208 in tent near hepa		12/24/2019	
193142-01-002-02-02	Post-Test	Room 208 in tent near risers		12/24/2019	
193142-01-002-02-03	Area Sample	Gym storage room (s.) at door		12/24/2019	
193142-01-002-02-04	Area Sample	Gym storage room (n.) at door		12/24/2019	
193142-01-002-02-05	Field Blank	Blank		12/24/2019	
193142-01-002-02-06	Field Blank	Blank		12/24/2019	

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	12/24/2019	22:19	
Send Reports To	School District of Philadelphia	12/24/2019	22:19	
Samples Taken By	Paul Scally	12/24/2019	22:19	
Analyzed By	P. Scally	12/24/2019	22:19	
Received By	P. Scally	12/24/2019	22:19	
Relinquished By	P. Scally	12/24/2019	22:19	
Transported By	P. Scally	12/24/2019	22:19	

Tile and




## **Results of Phase Contrast Microscopy**

Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 12/26/2019 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 12/26/2019 Oseroff, Samuel Collected By Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 12/26/2019

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-03-01	Post-Test	Room 209 in work area	08:57	11:15	138	9.96	1,374.48	2.0/100	<7.0	<0.002
193142-01-002-03-02	Post-Test	Room 209 in work area	08:57	11:16	139	9.96	1,384.44	3.0/100	<7.0	<0.002
193142-01-002-03-03	Area Sample	Room 201 outside closet	09:02	12:36	214	9.96	2,131.44	6.0/100	7.6	0.001
193142-01-002-03-04	Area Sample	Room 301 outside closet	09:08	12:37	209	9.96	2,081.64	31.5/100	40.1	0.007
193142-01-002-03-05	Post-Test	Basement art room (wraps)	10:08	13:15	187	9.96	1,862.52	4.0/100	<7.0	<0.001
193142-01-002-03-06	Area Sample	Gym office (prep)	12:33	14:38	125	9.96	1,245.00	7.0/100	8.9	0.003
193142-01-002-03-07	Area Sample	Room 201 outside closet	12:38	14:43	125	9.96	1,245.00	5.5/100	7.0	0.002
193142-01-002-03-08	Area Sample	Room 301 outside closet	12:40	14:46	126	9.96	1,254.96	12.5/100	15.9	0.005
193142-01-002-03-09	Post-Test	Gym hallway (wraps)	12:44	14:50	126	9.96	1,254.96	5.0/100	<7.0	<0.002
193142-01-002-03-10	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-03-11	Field Blank	Blank						0.0/100	<7.0	

Sample Count

11



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Sam Oseroff

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-03-01	Post-Test	Room 209 in work area		12/26/2019	
193142-01-002-03-02	Post-Test	Room 209 in work area		12/26/2019	
193142-01-002-03-03	Area Sample	Room 201 outside closet		12/26/2019	
193142-01-002-03-04	Area Sample	Room 301 outside closet		12/26/2019	
193142-01-002-03-05	Post-Test	Basement art room (wraps)		12/26/2019	
193142-01-002-03-06	Area Sample	Gym office (prep)		12/26/2019	
193142-01-002-03-07	Area Sample	Room 201 outside closet		12/26/2019	
193142-01-002-03-08	Area Sample	Room 301 outside closet		12/26/2019	
193142-01-002-03-09	Post-Test	Gym hallway (wraps)		12/26/2019	
193142-01-002-03-10	Field Blank	Blank		12/26/2019	
193142-01-002-03-11	Field Blank	Blank		12/26/2019	

#### Sample Count \_\_11\_

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	12/26/2019	14:59	
Send Reports To	School District of Philadelphia	12/26/2019	14:59	
Samples Taken By	Sam Oseroff	12/26/2019	14:59	
Analyzed By	Sam Oseroff	12/26/2019	00:00	
Received By	Sam Oseroff	12/26/2019	00:00	
Relinquished By	Sam Oseroff	12/26/2019	00:00	



Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 12/26/2019 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 12/26/2019 Scally, Paul Collected By Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 12/26/2019

						Flow Rate	Volume	Fibers	Fiber Density	
Sample Number	Sample Type	Location	Start	Stop	Mins	(LPM)	(L)	/Fields	f/mm²	Fiber /cc
193142-01-002-04-01	Area Sample	Gym teacher room in tent	15:05	19:05	240	5.00	1,200.00	3.5/100	<7.0	<0.002
193142-01-002-04-02	Area Sample	Gym teacher room at door	15:06	19:06	240	5.00	1,200.00	3.0/100	<7.0	<0.002
193142-01-002-04-03	Area Sample	1st floor hallway at fountain	15:46	19:07	201	6.00	1,206.00	1.5/100	<7.0	<0.002
193142-01-002-04-04	Area Sample	Room 111 at door	15:47	19:08	201	6.00	1,206.00	0.5/100	<7.0	<0.002
193142-01-002-04-05	Area Sample	Gym storage room in tent	17:00	19:01	121	10.00	1,210.00	3.0/100	<7.0	<0.002
193142-01-002-04-06	Area Sample	Gym storage room at door	17:01	19:03	122	9.90	1,207.80	3.5/100	<7.0	<0.002
193142-01-002-04-07	Post-Test	Gym teacher room above hepa	19:05	21:06	121	10.00	1,210.00	3.5/100	<7.0	<0.002
193142-01-002-04-08	Post-Test	Gym teacher room in tent	19:06	21:08	122	9.90	1,207.80	3.5/100	<7.0	<0.002
193142-01-002-04-09	Area Sample	Gym storage room at hepa	19:07	21:09	122	10.00	1,220.00	5.5/100	7.0	0.002
193142-01-002-04-10	Area Sample	Gym storage room at entrance	19:08	21:10	122	9.90	1,207.80	5.5/100	7.0	0.002
193142-01-002-04-11	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-04-12	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count

\_\_\_\_



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

**Container** Cassette **Project** 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site
Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-04-01	Area Sample	Gym teacher room in tent		12/26/2019	
193142-01-002-04-02	Area Sample	Gym teacher room at door		12/26/2019	
193142-01-002-04-03	Area Sample	1st floor hallway at fountain		12/26/2019	
193142-01-002-04-04	Area Sample	Room 111 at door		12/26/2019	
193142-01-002-04-05	Area Sample	Gym storage room in tent		12/26/2019	
193142-01-002-04-06	Area Sample	Gym storage room at door		12/26/2019	
193142-01-002-04-07	Post-Test	Gym teacher room above hepa		12/26/2019	
193142-01-002-04-08	Post-Test	Gym teacher room in tent		12/26/2019	
193142-01-002-04-09	Area Sample	Gym storage room at hepa		12/26/2019	
193142-01-002-04-10	Area Sample	Gym storage room at entrance		12/26/2019	
193142-01-002-04-11	Field Blank	Blank		12/26/2019	
193142-01-002-04-12	Field Blank	Blank		12/26/2019	

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	12/26/2019	23:12	
Send Reports To	School District of Philadelphia	12/26/2019	23:12	
Samples Taken By	Paul Scally	12/26/2019	23:12	
Analyzed By	P. Scally	12/26/2019	23:12	
Received By	P. Scally	12/26/2019	23:12	
Relinquished By	P. Scally	12/26/2019	23:12	
Transported By	P. Scally	12/26/2019	23:12	




Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 12/27/2019 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 12/27/2019 Collected By Oseroff, Samuel Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 12/27/2019

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-05-01	Area Sample	Room 201 outside closet	07:35	11:03	208	9.96	2,071.68	3.0/100	<7.0	<0.001
193142-01-002-05-02	Area Sample	Room 301 outside closet	07:38	10:08	150	9.96	1,494.00	20.0/100	25.5	0.007
193142-01-002-05-03	Post-Test	Art room in tent	09:30	11:38	128	9.96	1,274.88	2.0/100	<7.0	<0.002
193142-01-002-05-04	Post-Test	Art room in tent	09:31	11:38	127	9.96	1,264.92	3.0/100	<7.0	<0.002
193142-01-002-05-05	Post-Test	1st floor counselor office (wrap)	09:35	11:40	125	9.96	1,245.00	5.5/100	7.0	0.002
193142-01-002-05-06	Post-Test	1st floor mens restroom (wrap)	09:40	11:43	123	9.96	1,225.08	4.0/100	<7.0	<0.002
193142-01-002-05-07	Post-Test	1st floor boys restroom by new wing (wrap)	09:43	11:45	122	9.96	1,215.12	7.0/100	8.9	0.003
193142-01-002-05-08	Area Sample	301 outside work area at desk	10:09	12:18	129	9.96	1,284.84	13.5/100	17.2	0.005
193142-01-002-05-09	Area Sample	301 inside work area in closer	10:10	12:19	129	9.96	1,284.84	21.0/100	26.8	0.008
193142-01-002-05-10	Area Sample	208 outside closet (prep)	10:25	14:20	235	9.96	2,340.60	5.0/100	<7.0	<0.001
193142-01-002-05-11	Area Sample	Gym outside coach office	11:33	14:25	172	9.96	1,713.12	9.5/100	12.1	0.003
193142-01-002-05-12	Area Sample	Room 201 outside tent (prep)	12:22	14:28	126	9.96	1,254.96	6.0/100	7.6	0.002
193142-01-002-05-13	Area Sample	Room 304 (prep)	12:29	14:31	122	9.96	1,215.12	3.0/100	<7.0	<0.002
193142-01-002-05-14	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-05-15	Field Blank	Blank						0.0/100	<7.0	

Sample Count

\_15



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Sam Oseroff

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-05-01	Area Sample	Room 201 outside closet		12/27/2019	
193142-01-002-05-02	Area Sample	Room 301 outside closet		12/27/2019	
193142-01-002-05-03	Post-Test	Art room in tent		12/27/2019	
193142-01-002-05-04	Post-Test	Art room in tent		12/27/2019	
193142-01-002-05-05	Post-Test	1st floor counselor office (wrap)		12/27/2019	
193142-01-002-05-06	Post-Test	1st floor mens restroom (wrap)		12/27/2019	
193142-01-002-05-07	Post-Test	1st floor boys restroom by new wing (wrap)		12/27/2019	
193142-01-002-05-08	Area Sample	301 outside work area at desk		12/27/2019	
193142-01-002-05-09	Area Sample	301 inside work area in closer		12/27/2019	
193142-01-002-05-10	Area Sample	208 outside closet (prep)		12/27/2019	
193142-01-002-05-11	Area Sample	Gym outside coach office		12/27/2019	
193142-01-002-05-12	Area Sample	Room 201 outside tent (prep)		12/27/2019	
193142-01-002-05-13	Area Sample	Room 304 (prep)		12/27/2019	
193142-01-002-05-14	Field Blank	Blank		12/27/2019	
193142-01-002-05-15	Field Blank	Blank		12/27/2019	

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	12/27/2019	14:48	
Send Reports To	School District of Philadelphia	12/27/2019	14:48	



Samples Taken By	Sam Oseroff	12/27/2019 14:48
Received By	Sam Oseroff	12/27/2019 00:00
Relinquished By	Sam Oseroff	12/27/2019 00:00
Analyzed By	Sam Oseroff	12/27/2019 00:00

Tile and




## **Results of Phase Contrast Microscopy**

Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 12/27/2019 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 12/27/2019 Scally, Paul Collected By Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 12/27/2019

						Flow Rate	Volume	Fibers	Fiber Density	
Sample Number	Sample Type	Location	Start	Stop	Mins	(LPM)	(L)	/Fields	f/mm²	Fiber /cc
193142-01-002-06-01	Area Sample	201 in closet	15:20	17:22	122	9.90	1,207.80	11.0/100	14.0	0.004
193142-01-002-06-02	Post-Test	211 at closet	15:25	17:26	121	10.00	1,210.00	3.0/100	<7.0	<0.002
193142-01-002-06-03	Post-Test	Gym at E. Storage Room	15:30	17:30	120	10.00	1,200.00	6.5/100	8.3	0.003
193142-01-002-06-04	Post-Test	Gym at E. Storage Room	15:31	17:31	120	10.00	1,200.00	5.0/100	<7.0	<0.002
193142-01-002-06-05	Post-Test	212 at desk	15:33	17:36	123	9.80	1,205.40	6.5/100	8.3	0.003
193142-01-002-06-06	Area Sample	304 at center	16:00	18:30	150	8.00	1,200.00	5.0/100	<7.0	<0.002
193142-01-002-06-07	Post-Test	213 at screen	17:26	19:30	124	9.80	1,215.20	2.0/100	<7.0	< 0.002
193142-01-002-06-08	Post-Test	111 closet in tent	18:15	20:25	130	10.00	1,300.00	6.5/100	8.3	0.002
193142-01-002-06-09	Post-Test	111 closet at riser	18:16	20:26	130	10.00	1,300.00	8.0/100	10.2	0.003
193142-01-002-06-10	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-06-11	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count

11



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Q-cueta

Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site
Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

Sample Number	Sample Type	Location	Received Condition	Date	Notes
					Hotes
193142-01-002-06-01	Area Sample	201 in closet	•	12/27/2019	
193142-01-002-06-02	Post-Test	211 at closet	•	12/27/2019	
193142-01-002-06-03	Post-Test	Gym at E. Storage Room	•	12/27/2019	
193142-01-002-06-04	Post-Test	Gym at E. Storage Room	,	12/27/2019	
193142-01-002-06-05	Post-Test	212 at desk	•	12/27/2019	
193142-01-002-06-06	Area Sample	304 at center	•	12/27/2019	
193142-01-002-06-07	Post-Test	213 at screen	•	12/27/2019	
193142-01-002-06-08	Post-Test	111 closet in tent	•	12/27/2019	
193142-01-002-06-09	Post-Test	111 closet at riser	•	12/27/2019	
193142-01-002-06-10	Field Blank	Blank	•	12/27/2019	
193142-01-002-06-11	Field Blank	Blank	•	12/27/2019	

Sample Count \_\_11\_

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	12/27/2019	23:22	
Send Reports To	School District of Philadelphia	12/27/2019	23:22	
Samples Taken By	Paul Scally	12/27/2019	23:22	
Analyzed By	P. Scally	12/27/2019	23:22	
Received By	P. Scally	12/27/2019	23:22	
Relinquished By	P. Scally	12/27/2019	23:22	
Transported By	P. Scally	12/27/2019	23:22	




School District of Philadelphia Carnell Elementary School - 1100 Sample Date Client Site Address 12/28/2019 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 12/28/2019 19111 Sample Analysis Date(s) Collected By Criterion Laboratories, Inc. Analyzed By Oseroff, Samuel 12/28/2019

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-07-01	Post-Test	301 closet in work area	08:18	10:32	134	9.96	1,334.64	4.0/100	<7.0	<0.002
193142-01-002-07-02	Post-Test	301 closet in work area	08:19	10:32	133	9.96	1,324.68	2.0/100	<7.0	<0.002
193142-01-002-07-03	Area Sample	304 in tent	08:23	10:26	123	9.96	1,225.08	11.0/100	14.0	0.004
193142-01-002-07-04	Area Sample	304 outside tent	08:23	10:26	123	9.96	1,225.08	4.0/100	<7.0	< 0.002
193142-01-002-07-05	Area Sample	201 inside tent	08:30	10:42	132	9.96	1,314.72	13.5/100	17.2	0.005
193142-01-002-07-06	Area Sample	201 outside decon	08:31	10:43	132	9.96	1,314.72	6.0/100	7.6	0.002
193142-01-002-07-07	Area Sample	208 outside closet (prep)	08:37	12:06	209	9.96	2,081.64	4.5/100	<7.0	<0.001
193142-01-002-07-08	Area Sample	113 outside closet (prep)	08:45	12:08	203	9.96	2,021.88	6.0/100	7.6	0.001
193142-01-002-07-09	Post-Test	304 in tent	09:42	12:00	138	9.96	1,374.48	5.0/100	<7.0	<0.002
193142-01-002-07-10	Post-Test	304 in tent	09:43	12:00	137	9.96	1,364.52	7.0/100	8.9	0.003
193142-01-002-07-11	Area Sample	208 outside closet (prep)	12:07	14:21	134	9.96	1,334.64	6.0/100	7.6	0.002
193142-01-002-07-12	Area Sample	113 outside closet	12:16	14:24	128	9.96	1,274.88	9.0/100	11.5	0.003
193142-01-002-07-13	Area Sample	113 in work area closet	12:18	14:24	126	9.96	1,254.96	15.5/100	19.7	0.006
193142-01-002-07-14	Post-Test	Hallway between 210&stairwell (repair)	13:05	15:13	128	9.96	1,274.88	2.5/100	<7.0	<0.002
193142-01-002-07-15	Post-Test	210 (repair)	13:00	15:14	134	9.96	1,334.64	2.0/100	<7.0	<0.002
193142-01-002-07-16	Post-Test	Nurses office (repair)	13:07	15:16	129	9.96	1,284.84	4.0/100	<7.0	<0.002
193142-01-002-07-17	Post-Test	305 in tent	14:07	16:23	136	9.96	1,354.56	5.0/100	<7.0	<0.002
193142-01-002-07-18	Post-Test	305 in tent	14:08	16:24	136	9.96	1,354.56	5.5/100	7.0	0.002
193142-01-002-07-19	Post-Test	113 in tent	14:37	16:49	132	9.96	1,314.72	7.5/100	9.6	0.003
193142-01-002-07-20	Post-Test	113 in tent	14:38	16:49	131	9.96	1,304.76	5.0/100	<7.0	<0.002
193142-01-002-07-21	Post-Test	206 by windows (repair)	15:19	17:25	126	9.96	1,254.96	3.0/100	<7.0	<0.002
193142-01-002-07-22	Post-Test	205/IMC by office door (repair)	15:21	17:29	128	9.96	1,274.88	3.0/100	<7.0	<0.002
193142-01-002-07-23	Post-Test	203 by desk (repair)	15:24	17:33	129	9.96	1,284.84	2.0/100	<7.0	<0.002
193142-01-002-07-24	Post-Test	202 by windows (repair)	15:28	17:38	130	9.96	1,294.80	5.0/100	<7.0	<0.002
193142-01-002-07-25	Post-Test	201 by windows (repair)	15:30	17:41	131	9.96	1,304.76	2.5/100	<7.0	<0.002
193142-01-002-07-26	Post-Test	218/assistant principal office (repair)	15:33	17:43	130	9.96	1,294.80	2.0/100	<7.0	<0.002
193142-01-002-07-27	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-07-28	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-07-29	Field Blank	Blank						0.0/100	<7.0	



Client	School District of Philadelphia	Site Address	Carnell Elementary School - 1100	Sample Date	12/28/2019
Project #	193142		Devereaux Avenue, Philadelphia, PA 19111	Sample Received Date	12/28/2019
Collected By	Criterion Laboratories, Inc.	Analyzed By	Oseroff, Samuel	Sample Analysis Date(s)	12/28/2019



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Sam Oseroff

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

Sample Number   Sample Type   Location   Condition   Date   Notes				Received		
area  193142-01-002-07-02	Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-07-02	193142-01-002-07-01	Post-Test	301 closet in work		12/28/2019	
193142-01-002-07-03						
193142-01-002-07-03         Area Sample         304 in tent         12/28/2019           193142-01-002-07-04         Area Sample         304 outside tent         12/28/2019           193142-01-002-07-05         Area Sample         201 inside tent         12/28/2019           193142-01-002-07-06         Area Sample         201 outside decon         12/28/2019           193142-01-002-07-07         Area Sample         208 outside closet         12/28/2019           193142-01-002-07-08         Area Sample         113 outside closet         12/28/2019           193142-01-002-07-09         Post-Test         304 in tent         12/28/2019           193142-01-002-07-10         Post-Test         304 in tent         12/28/2019           193142-01-002-07-11         Area Sample         208 outside closet         12/28/2019           193142-01-002-07-12         Area Sample         113 outside closet         12/28/2019           193142-01-002-07-13         Area Sample         113 outside closet         12/28/2019           193142-01-002-07-14         Post-Test         Hallway between         12/28/2019           193142-01-002-07-15         Post-Test         210 (repair)         12/28/2019           193142-01-002-07-15         Post-Test         210 (repair)         12/28/2019	193142-01-002-07-02	Post-Test	301 closet in work		12/28/2019	
193142-01-002-07-04   Area Sample   201 inside tent   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   13/242-01-002-07-08   Area Sample   208 outside closet   12/28/2019   12/28/2019   13/242-01-002-07-09   Post-Test   304 in tent   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   12/28/2019   13/242-01-002-07-12   Area Sample   113 outside closet   12/28/2019   12/28/2019   13/242-01-002-07-13   Area Sample   113 outside closet   12/28/2019   12/28/2019   13/242-01-002-07-14   Post-Test   13/28/2019   13/242-01-002-07-15   Post-Test   14/28/2019   12/28/2019   12/28/2019   13/242-01-002-07-16   Post-Test   Nurses office   12/28/2019   12/28/2019   193142-01-002-07-17   Post-Test   305 in tent   12/28/2019   193142-01-002-07-19   Post-Test   113 in tent   12/28/2019   193142-01-002-07-19   Post-Test   113 in tent   12/28/2019   193142-01-002-07-20   Post-Test   113 in tent   12/28/2019   193142-01-002-07-20   Post-Test   113 in tent   12/28/2019   193142-01-002-07-20   Post-Test   113 in tent   12/28/2019   193142-01-002-07-21   Post-Test   113 in tent   12/28/2019   193142-01-002-07-22   Post-Test   205/IMC by office   12/28/2019   12/28/2019   12/28/2019   193142-01-002-07-22   Post-Test   205/IMC by office   12/28/2019						
193142-01-002-07-05						
193142-01-002-07-06						
193142-01-002-07-08	193142-01-002-07-05		201 inside tent		12/28/2019	
(prep)  193142-01-002-07-08			-			
193142-01-002-07-08	193142-01-002-07-07	Area Sample			12/28/2019	
(prep)   193142-01-002-07-09   Post-Test   304 in tent   12/28/2019   193142-01-002-07-10   Post-Test   304 in tent   12/28/2019   193142-01-002-07-11   Area Sample   208 outside closet   12/28/2019   (prep)   193142-01-002-07-12   Area Sample   113 outside closet   12/28/2019   193142-01-002-07-13   Area Sample   113 in work area   12/28/2019   closet   193142-01-002-07-14   Post-Test   Hallway between   12/28/2019   210&stairwell (repair)   193142-01-002-07-15   Post-Test   210 (repair)   12/28/2019   193142-01-002-07-16   Post-Test   Nurses office   12/28/2019   193142-01-002-07-17   Post-Test   305 in tent   12/28/2019   193142-01-002-07-18   Post-Test   305 in tent   12/28/2019   193142-01-002-07-19   Post-Test   113 in tent   12/28/2019   193142-01-002-07-20   Post-Test   113 in tent   12/28/2019   193142-01-002-07-21   Post-Test   206 by windows   12/28/2019   193142-01-002-07-22   Post-Test   205/IMC by office   12/28/2019   12/28/2019   193142-01-002-07-22   Post-Test   205/IMC by office   12/28/2019   12/						
193142-01-002-07-10       Post-Test       304 in tent       12/28/2019         193142-01-002-07-11       Area Sample       208 outside closet       12/28/2019         193142-01-002-07-12       Area Sample       113 outside closet       12/28/2019         193142-01-002-07-13       Area Sample       113 in work area       12/28/2019         193142-01-002-07-14       Post-Test       Hallway between       12/28/2019         193142-01-002-07-15       Post-Test       210 (repair)       12/28/2019         193142-01-002-07-16       Post-Test       Nurses office (repair)       12/28/2019         193142-01-002-07-17       Post-Test       305 in tent       12/28/2019         193142-01-002-07-18       Post-Test       305 in tent       12/28/2019         193142-01-002-07-19       Post-Test       113 in tent       12/28/2019         193142-01-002-07-20       Post-Test       113 in tent       12/28/2019         193142-01-002-07-21       Post-Test       206 by windows (repair)       12/28/2019         193142-01-002-07-22       Post-Test       205/IMC by office       12/28/2019	193142-01-002-07-08	Area Sample			12/28/2019	
193142-01-002-07-11 Area Sample 208 outside closet (prep)  193142-01-002-07-12 Area Sample 113 outside closet 12/28/2019  193142-01-002-07-13 Area Sample 113 in work area 12/28/2019  193142-01-002-07-14 Post-Test Hallway between 12/28/2019  193142-01-002-07-15 Post-Test 210 (repair) 12/28/2019  193142-01-002-07-16 Post-Test Nurses office 12/28/2019  193142-01-002-07-17 Post-Test 305 in tent 12/28/2019  193142-01-002-07-18 Post-Test 305 in tent 12/28/2019  193142-01-002-07-19 Post-Test 113 in tent 12/28/2019  193142-01-002-07-20 Post-Test 113 in tent 12/28/2019  193142-01-002-07-21 Post-Test 206 by windows 12/28/2019  193142-01-002-07-22 Post-Test 205/IMC by office 12/28/2019	193142-01-002-07-09	Post-Test	304 in tent		12/28/2019	
(prep)  193142-01-002-07-12	193142-01-002-07-10	Post-Test	304 in tent		12/28/2019	
193142-01-002-07-13 Area Sample 113 in work area closet  193142-01-002-07-14 Post-Test Hallway between 12/28/2019 210&stairwell (repair)  193142-01-002-07-15 Post-Test 210 (repair) 12/28/2019 193142-01-002-07-16 Post-Test Nurses office 12/28/2019 193142-01-002-07-17 Post-Test 305 in tent 12/28/2019 193142-01-002-07-18 Post-Test 305 in tent 12/28/2019 193142-01-002-07-19 Post-Test 113 in tent 12/28/2019 193142-01-002-07-20 Post-Test 113 in tent 12/28/2019 193142-01-002-07-21 Post-Test 206 by windows (repair) 193142-01-002-07-22 Post-Test 205/IMC by office 12/28/2019	193142-01-002-07-11	Area Sample			12/28/2019	
193142-01-002-07-14	193142-01-002-07-12	Area Sample	113 outside closet		12/28/2019	
210&stairwell (repair)  193142-01-002-07-15 Post-Test 210 (repair) 12/28/2019  193142-01-002-07-16 Post-Test Nurses office (repair)  193142-01-002-07-17 Post-Test 305 in tent 12/28/2019  193142-01-002-07-18 Post-Test 305 in tent 12/28/2019  193142-01-002-07-19 Post-Test 113 in tent 12/28/2019  193142-01-002-07-20 Post-Test 113 in tent 12/28/2019  193142-01-002-07-21 Post-Test 206 by windows 12/28/2019  193142-01-002-07-22 Post-Test 205/IMC by office 12/28/2019	193142-01-002-07-13	Area Sample			12/28/2019	
193142-01-002-07-16       Post-Test       Nurses office (repair)         193142-01-002-07-17       Post-Test       305 in tent       12/28/2019         193142-01-002-07-18       Post-Test       305 in tent       12/28/2019         193142-01-002-07-19       Post-Test       113 in tent       12/28/2019         193142-01-002-07-20       Post-Test       113 in tent       12/28/2019         193142-01-002-07-21       Post-Test       206 by windows (repair)       12/28/2019         193142-01-002-07-22       Post-Test       205/IMC by office       12/28/2019	193142-01-002-07-14	Post-Test	210&stairwell		12/28/2019	
(repair)         193142-01-002-07-17       Post-Test       305 in tent       12/28/2019         193142-01-002-07-18       Post-Test       305 in tent       12/28/2019         193142-01-002-07-19       Post-Test       113 in tent       12/28/2019         193142-01-002-07-20       Post-Test       113 in tent       12/28/2019         193142-01-002-07-21       Post-Test       206 by windows (repair)       12/28/2019         193142-01-002-07-22       Post-Test       205/IMC by office       12/28/2019	193142-01-002-07-15	Post-Test	210 (repair)		12/28/2019	
193142-01-002-07-18       Post-Test       305 in tent       12/28/2019         193142-01-002-07-19       Post-Test       113 in tent       12/28/2019         193142-01-002-07-20       Post-Test       113 in tent       12/28/2019         193142-01-002-07-21       Post-Test       206 by windows (repair)       12/28/2019         193142-01-002-07-22       Post-Test       205/IMC by office       12/28/2019	193142-01-002-07-16	Post-Test			12/28/2019	
193142-01-002-07-19       Post-Test       113 in tent       12/28/2019         193142-01-002-07-20       Post-Test       113 in tent       12/28/2019         193142-01-002-07-21       Post-Test       206 by windows (repair)       12/28/2019         193142-01-002-07-22       Post-Test       205/IMC by office       12/28/2019	193142-01-002-07-17	Post-Test			12/28/2019	
193142-01-002-07-20       Post-Test       113 in tent       12/28/2019         193142-01-002-07-21       Post-Test       206 by windows (repair)       12/28/2019         193142-01-002-07-22       Post-Test       205/IMC by office       12/28/2019	193142-01-002-07-18	Post-Test	305 in tent		12/28/2019	
193142-01-002-07-21 Post-Test 206 by windows 12/28/2019 (repair) 193142-01-002-07-22 Post-Test 205/IMC by office 12/28/2019	193142-01-002-07-19	Post-Test	113 in tent		12/28/2019	
(repair) 193142-01-002-07-22 Post-Test 205/IMC by office 12/28/2019	193142-01-002-07-20	Post-Test	113 in tent		12/28/2019	
193142-01-002-07-22 Post-Test 205/IMC by office 12/28/2019	193142-01-002-07-21	Post-Test			12/28/2019	
	193142-01-002-07-22	Post-Test	205/IMC by office		12/28/2019	



193142-01-002-07-23	Post-Test	203 by desk (repair)	12/28/2019
193142-01-002-07-24	Post-Test	202 by windows (repair)	12/28/2019
193142-01-002-07-25	Post-Test	201 by windows (repair)	12/28/2019
193142-01-002-07-26	Post-Test	218/assistant principal office (repair)	12/28/2019
193142-01-002-07-27	Field Blank	Blank <sup>′</sup>	12/28/2019
193142-01-002-07-28	Field Blank	Blank	12/28/2019
193142-01-002-07-29	Field Blank	Blank	12/28/2019


Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	12/28/2019	18:05	
Send Reports To	School District of Philadelphia	12/28/2019	18:05	
Samples Taken By	Sam Oseroff	12/28/2019	18:05	
Received By	Sam Oseroff	12/28/2019	00:00	
Relinquished By	Sam Oseroff	12/28/2019	00:00	
Analyzed By	Sam Oseroff	12/28/2019	00:00	



Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 12/29/2019 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 12/29/2019 Scally, Paul Collected By Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 12/29/2019

						Flow Rate	Volume	Fibers	Fiber Density	
Sample Number	Sample Type	Location	Start	Stop	Mins	(LPM)	(L)	/Fields	f/mm²	Fiber /cc
193142-01-002-08-01	Area Sample	310 at tent	07:10	10:31	201	6.00	1,206.00	1.5/100	<7.0	<0.002
193142-01-002-08-02	Area Sample	208 at desk	07:15	10:35	200	6.00	1,200.00	3.0/100	<7.0	<0.002
193142-01-002-08-03	Area Sample	213 at entrance	07:18	10:39	201	6.00	1,206.00	4.5/100	<7.0	<0.002
193142-01-002-08-04	Area Sample	312 at center	07:20	10:40	200	6.00	1,200.00	4.5/100	<7.0	<0.002
193142-01-002-08-05	Post-Test	310 in tent above hepa	10:31	12:32	121	10.00	1,210.00	11.5/100	14.7	0.005
193142-01-002-08-06	Post-Test	310 in tent at riser	10:32	12:34	122	9.90	1,207.80	11.5/100	14.7	0.005
193142-01-002-08-07	Area Sample	Basement near B-5	10:36	13:07	151	8.00	1,208.00	4.0/100	<7.0	<0.002
193142-01-002-08-08	Area Sample	208 at door	10:38	13:09	151	8.00	1,208.00	5.5/100	7.0	0.002
193142-01-002-08-09	Area Sample	213 at entrance	10:39	13:13	154	8.00	1,232.00	4.5/100	<7.0	<0.002
193142-01-002-08-10	Area Sample	312 at entrance	10:41	13:15	154	8.00	1,232.00	6.5/100	8.3	0.003
193142-01-002-08-11	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-08-12	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count 12



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site
Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

Sample Number	Sample Type	Location	Received Condition	Date	Notes
193142-01-002-08-01	Area Sample	310 at tent		12/30/2019	
193142-01-002-08-02	Area Sample	208 at desk		12/30/2019	
193142-01-002-08-03	Area Sample	213 at entrance		12/30/2019	
193142-01-002-08-04	Area Sample	312 at center		12/30/2019	
193142-01-002-08-05	Post-Test	310 in tent above hepa		12/30/2019	
193142-01-002-08-06	Post-Test	310 in tent at riser		12/30/2019	
193142-01-002-08-07	Area Sample	Basement near B-5		12/30/2019	
193142-01-002-08-08	Area Sample	208 at door		12/30/2019	
193142-01-002-08-09	Area Sample	213 at entrance		12/30/2019	
193142-01-002-08-10	Area Sample	312 at entrance		12/30/2019	
193142-01-002-08-11	Field Blank	Blank		12/30/2019	
193142-01-002-08-12	Field Blank	Blank		12/30/2019	

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	12/29/2019	15:15	
Send Reports To	School District of Philadelphia	12/29/2019	15:15	
Samples Taken By	Paul Scally	12/29/2019	15:15	
Analyzed By	P. Scally	12/29/2019	15:15	
Received By	P. Scally	12/29/2019	15:15	
Relinquished By	P. Scally	12/29/2019	15:15	
Transported By	P. Scally	12/29/2019	15:15	



School District of Philadelphia Carnell Elementary School - 1100 Sample Date Client Site Address 12/30/2019 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 12/30/2019 19111 Collected By Criterion Laboratories, Inc. Analyzed By Oseroff, Samuel Sample Analysis Date(s) 12/30/2019

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-09-01	Post-Test	208 closet in work area	07:34	09:54	140	9.96	1.394.40	5.0/100	<7.0	<0.002
193142-01-002-09-02	Post-Test	208 closet in work area	07:35	09:54	139	9.96	1,384.44	6.0/100	7.6	0.002
193142-01-002-09-03	Post-Test	B5 in work area	07:41	09:45	124	9.96	1,235.04	3.5/100	<7.0	<0.002
193142-01-002-09-04	Post-Test	B5 in work area	07:41	09:46	125	9.96	1,245.00	5.0/100	<7.0	<0.002
193142-01-002-09-05	Post-Test	313 (repairs)	08:02	10:20	138	9.96	1,374.48	3.0/100	<7.0	<0.002
193142-01-002-09-06	Post-Test	Storage room 313C (repairs)	08:05	10:16	131	9.96	1,304.76	6.0/100	7.6	0.002
193142-01-002-09-07	Post-Test	312 (repairs)	08:09	10:22	133	9.96	1,324.68	2.5/100	<7.0	<0.002
193142-01-002-09-08	Post-Test	311 (repairs)	08:12	10:24	132	9.96	1,314.72	4.0/100	<7.0	< 0.002
193142-01-002-09-09	Post-Test	310 (repairs)	08:15	10:26	131	9.96	1,304.76	2.0/100	<7.0	<0.002
193142-01-002-09-10	Post-Test	Basement custodial closet (repairs)	10:06	12:22	136	9.96	1,354.56	5.0/100	<7.0	< 0.002
193142-01-002-09-11	Post-Test	B4 (repairs)	10:08	12:25	137	9.96	1,364.52	4.5/100	<7.0	<0.002
193142-01-002-09-12	Post-Test	B7 (repairs)	10:12	12:28	136	9.96	1,354.56	5.0/100	<7.0	<0.002
193142-01-002-09-13	Area Sample	312 in work area	11:22	13:25	123	9.96	1,225.08	22.5/100	28.7	0.009
193142-01-002-09-14	Area Sample	312 outside work area	11:23	13:25	122	9.96	1,215.12	6.0/100	7.6	0.002
193142-01-002-09-15	Area Sample	213 in work area	11:28	13:44	136	9.96	1,354.56	16.5/100	21.0	0.006
193142-01-002-09-16	Area Sample	213 outside work area	11:29	13:45	136	9.96	1,354.56	8.5/100	10.8	0.003
193142-01-002-09-17	Post-Test	312 in work area	12:50	15:00	130	9.96	1,294.80	6.5/100	8.3	0.002
193142-01-002-09-18	Post-Test	312 in work area	12:50	15:00	130	9.96	1,294.80	9.0/100	11.5	0.003
193142-01-002-09-19	Post-Test	213 in work area	13:45	16:00	135	9.96	1,344.60	6.0/100	7.6	0.002
193142-01-002-09-20	Post-Test	213 in work area	13:45	16:00	135	9.96	1,344.60	5.0/100	<7.0	<0.002
193142-01-002-09-21	Area Sample	306 in work area by windows	14:32	18:15	223	9.96	2,221.08	27.0/100	34.4	0.006
193142-01-002-09-22	Area Sample	306 outside work area	14:32	18:15	223	9.96	2,221.08	9.0/100	11.5	0.002
193142-01-002-09-23	Post-Test	Basement Hall by art room	14:40	16:56	136	9.96	1,354.56	6.0/100	7.6	0.002
193142-01-002-09-24	Post-Test	Basement Hall by new wing	14:43	16:59	136	9.96	1,354.56	4.0/100	<7.0	<0.002
193142-01-002-09-25	Post-Test	Basement Hall by B2	14:49	17:03	134	9.96	1,334.64	7.0/100	8.9	0.003
193142-01-002-09-26	Post-Test	Basement hallway by large storage room	14:51	17:06	135	9.96	1,344.60	5.5/100	7.0	0.002
193142-01-002-09-27	Post-Test	Gym kitchen side	15:36	17:50	134	9.96	1,334.64	3.0/100	<7.0	<0.002
193142-01-002-09-28	Post-Test	Gym art room side	15:39	17:51	132	9.96	1,314.72	7.0/100	8.9	0.003
193142-01-002-09-29	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-09-30	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-09-31	Field Blank	Blank						0.0/100	<7.0	

Sample Count 31

Report Date: 1/3/2020



Client	School District of Philadelphia	Site Address	Carnell Elementary School - 1100	Sample Date	12/30/2019
Project #	193142		Devereaux Avenue, Philadelphia, PA 19111	Sample Received Date	12/30/2019
Collected By	Criterion Laboratories, Inc.	Analyzed By	Oseroff, Samuel	Sample Analysis Date(s)	12/30/2019

James A. Weltz, CIH, Technical Director

Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

**Container** Cassette **Project** 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Sam Oseroff

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-09-01	Post-Test	208 closet in work area		12/30/2019	
193142-01-002-09-02	Post-Test	208 closet in work area		12/30/2019	
193142-01-002-09-03	Post-Test	B5 in work area		12/30/2019	
193142-01-002-09-04	Post-Test	B5 in work area		12/30/2019	
193142-01-002-09-05	Post-Test	313 (repairs)		12/30/2019	
193142-01-002-09-06	Post-Test	Storage room 313C (repairs)		12/30/2019	
193142-01-002-09-07	Post-Test	312 (repairs)		12/30/2019	
193142-01-002-09-08	Post-Test	311 (repairs)		12/30/2019	
193142-01-002-09-09	Post-Test	310 (repairs)		12/30/2019	
193142-01-002-09-10	Post-Test	Basement custodial closet (repairs)		12/30/2019	
193142-01-002-09-11	Post-Test	B4 (repairs)		12/30/2019	
193142-01-002-09-12	Post-Test	B7 (repairs)		12/30/2019	
193142-01-002-09-13	Area Sample	312 in work area		12/30/2019	
193142-01-002-09-14	Area Sample	312 outside work area		12/30/2019	
193142-01-002-09-15	Area Sample	213 in work area		12/30/2019	
193142-01-002-09-16	Area Sample	213 outside work area		12/30/2019	
193142-01-002-09-17	Post-Test	312 in work area		12/30/2019	
193142-01-002-09-18	Post-Test	312 in work area		12/30/2019	
193142-01-002-09-19	Post-Test	213 in work area		12/30/2019	
193142-01-002-09-20	Post-Test	213 in work area		12/30/2019	
193142-01-002-09-21	Area Sample	306 in work area by windows		12/30/2019	
193142-01-002-09-22	Area Sample	306 outside work area		12/30/2019	
193142-01-002-09-23	Post-Test	Basement Hall by art room		12/30/2019	



193142-01-002-09-24	Post-Test	Basement Hall by new wing	12/30/2019
193142-01-002-09-25	Post-Test	Basement Hall by B2	12/30/2019
193142-01-002-09-26	Post-Test	Basement hallway by large storage room	12/30/2019
193142-01-002-09-27	Post-Test	Gym kitchen side	12/30/2019
193142-01-002-09-28	Post-Test	Gym art room side	12/30/2019
193142-01-002-09-29	Field Blank	Blank	12/30/2019
193142-01-002-09-30	Field Blank	Blank	12/30/2019
193142-01-002-09-31	Field Blank	Blank	12/30/2019

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	12/30/2019	18:30	
Send Reports To	School District of Philadelphia	12/30/2019	18:30	
Samples Taken By	Sam Oseroff	12/30/2019	18:30	
Received By	Sam Oseroff	12/30/2019	00:00	
Relinquished By	Sam Oseroff	12/30/2019	00:00	
Analyzed By	Sam Oseroff	12/30/2019	00:00	




Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 12/31/2019 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 12/31/2019 Collected By Oseroff, Samuel Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 12/31/2019

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-10-01	Post-Test	306 in tent	07:23	09:48	145	9.96	1,444.20	4.0/100	<7.0	<0.002
193142-01-002-10-02	Post-Test	306 in tent	07:24	09:48	144	9.96	1,434.24	4.0/100	<7.0	<0.002
193142-01-002-10-03	Post-Test	Lunch room (repairs)	07:33	09:53	140	9.96	1,394.40	3.0/100	<7.0	<0.002
193142-01-002-10-04	Post-Test	110 by desk (repair)	09:58	12:11	133	9.96	1,324.68	5.0/100	<7.0	<0.002
193142-01-002-10-05	Post-Test	109 center (repair)	10:02	12:13	131	9.96	1,304.76	4.5/100	<7.0	<0.002
193142-01-002-10-06	Post-Test	107 by desk (repair)	10:05	12:16	131	9.96	1,304.76	6.0/100	7.6	0.002
193142-01-002-10-07	Post-Test	103 by windows (repair)	10:08	12:20	132	9.96	1,314.72	3.0/100	<7.0	<0.002
193142-01-002-10-08	Post-Test	101 at bathroom door (repair)	10:12	12:23	131	9.96	1,304.76	2.5/100	<7.0	<0.002
193142-01-002-10-09	Post-Test	B5 rear wall (repair)	10:19	12:30	131	9.96	1,304.76	4.0/100	<7.0	<0.002
193142-01-002-10-10	Post-Test	B6 by desk (repair)	10:21	12:31	130	9.96	1,294.80	5.0/100	<7.0	<0.002
193142-01-002-10-11	Post-Test	Staff men's restroom 2nd floor new wing	10:32	12:38	126	9.96	1,254.96	2.0/100	<7.0	<0.002
193142-01-002-10-12	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-10-13	Field Blank	Blank						0.0/100	<7.0	

Sample Count

13



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

**Container** Cassette **Project** 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Sam Oseroff

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-10-01	Post-Test	306 in tent		12/31/2019	
193142-01-002-10-02	Post-Test	306 in tent		12/31/2019	
193142-01-002-10-03	Post-Test	Lunch room (repairs)		12/31/2019	
193142-01-002-10-04	Post-Test	110 by desk (repair)		12/31/2019	
193142-01-002-10-05	Post-Test	109 center (repair)		12/31/2019	
193142-01-002-10-06	Post-Test	107 by desk (repair)		12/31/2019	
193142-01-002-10-07	Post-Test	103 by windows (repair)		12/31/2019	
193142-01-002-10-08	Post-Test	101 at bathroom door (repair)		12/31/2019	
193142-01-002-10-09	Post-Test	B5 rear wall (repair)		12/31/2019	
193142-01-002-10-10	Post-Test	B6 by desk (repair)		12/31/2019	
193142-01-002-10-11	Post-Test	Staff men's restroom 2nd floor new wing		12/31/2019	
193142-01-002-10-12	Field Blank	Blank		12/31/2019	
193142-01-002-10-13	Field Blank	Blank		12/31/2019	

Sample Count \_13\_

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	12/31/2019	12:54	
Send Reports To	School District of Philadelphia	12/31/2019	12:54	
Samples Taken By	Sam Oseroff	12/31/2019	12:54	
Analyzed By	Sam Oseroff	12/31/2019	00:00	
Received By	Sam Oseroff	12/31/2019	00:00	
Relinquished By	Sam Oseroff	12/31/2019	00:00	



Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 1/2/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 1/2/2020 Sample Received Date Scally, Paul Collected By Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 1/3/2020

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-12-01	Area Sample	108 at closet	16:20	18:23	123	9.80	1,205.40	2.0/100	<7.0	<0.002
193142-01-002-12-02	Area Sample	108 at entrance	16:21	18:26	125	9.90	1,237.50	4.0/100	<7.0	<0.002
193142-01-002-12-03	Post-Test	104 at screen	18:25	20:56	151	8.90	1,343.90	2.0/100	<7.0	<0.002
193142-01-002-12-04	Post-Test	At Main Office	18:26	20:58	152	8.00	1,216.00	1.0/100	<7.0	< 0.002
193142-01-002-12-05	Area Sample	At gym storage room	18:30	21:00	150	8.00	1,200.00	2.0/100	<7.0	<0.002
193142-01-002-12-06	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-12-07	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count



James A. Weltz, CIH, Technical Director

Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Q-cueta

Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-12-01	Area Sample	108 at closet		1/3/2020	
193142-01-002-12-02	Area Sample	108 at entrance		1/3/2020	
193142-01-002-12-03	Post-Test	104 at screen		1/3/2020	
193142-01-002-12-04	Post-Test	At Main Office		1/3/2020	
193142-01-002-12-05	Area Sample	At gym storage room		1/3/2020	
193142-01-002-12-06	Field Blank	Blank		1/3/2020	
193142-01-002-12-07	Field Blank	Blank		1/3/2020	

Sample Count \_\_7\_


Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/2/2020	23:28	
Send Reports To	School District of Philadelphia	1/2/2020	23:28	
Samples Taken By	Paul Scally	1/2/2020	23:28	
Analyzed By	P. Scally	1/2/2020	23:28	
Received By	P. Scally	1/2/2020	23:28	
Relinquished By	P. Scally	1/2/2020	23:28	
Transported By	P. Scally	1/2/2020	23:28	



Client	School District of Philadelphia	Site Address	Carnell Elementary School - 1100	Sample Date	1/3/2020
Project #	193142		Devereaux Avenue, Philadelphia, PA 19111	Sample Received Date	1/3/2020
Collected By	Criterion Laboratories, Inc.	Analyzed By	Scally, Paul	Sample Analysis Date(s)	1/3/2020

						Flow Data	Valuma	Tib a ua	Fiber	
Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Density f/mm²	Fiber /cc
193142-01-002-14-01	Area Sample	314 at closet	15:08	16:38	90	10.00	900.00	1.0/100	<7.0	< 0.003
193142-01-002-14-02	Area Sample	301 at door near adjacent closet	15:09	16:40	91	10.00	910.00	1.0/100	<7.0	< 0.003
193142-01-002-14-03	Area Sample	107 at entrance	16:42	20:43	241	5.00	1,205.00	1.5/100	<7.0	<0.002
193142-01-002-14-04	Area Sample	103 at desk	16:43	20:45	242	5.00	1,210.00	1.0/100	<7.0	<0.002
193142-01-002-14-05	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-14-06	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count



6

Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Paul Scally

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

**Sample Notes** 

**Field Tech** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-14-01	Area Sample	314 at closet		1/3/2020	
193142-01-002-14-02	Area Sample	301 at door near adjacent closet		1/3/2020	
193142-01-002-14-03	Area Sample	107 at entrance		1/3/2020	
193142-01-002-14-04	Area Sample	103 at desk		1/3/2020	
193142-01-002-14-05	Field Blank	Blank		1/3/2020	
193142-01-002-14-06	Field Blank	Blank		1/3/2020	

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/3/2020	23:22	
Send Reports To	School District of Philadelphia	1/3/2020	23:22	
Samples Taken By	Paul Scally	1/3/2020	23:22	
Analyzed By	P. Scally	1/3/2020	23:22	
Received By	P. Scally	1/3/2020	23:22	
Relinquished By	P. Scally	1/3/2020	23:22	
Transported By	P. Scally	1/3/2020	23:22	

Tile and




## **Results of Phase Contrast Microscopy**

Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 1/4/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 1/4/2020 Scally, Paul 1/4/2020 Collected By Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s)

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Density f/mm²	Fiber /cc
193142-01-002-15-01	Post-Test	314 at vat-job	07:40	09:43	123	9.80	1,205.40	1.5/100	<7.0	<0.002
193142-01-002-15-02	Post-Test	3rd floor print-room at door	07:41	09:45	124	9.80	1,215.20	1.5/100	<7.0	<0.002
193142-01-002-15-03	Post-Test	313 at radiator	08:00	10:00	120	10.00	1,200.00	1.0/100	<7.0	<0.002
193142-01-002-15-04	Post-Test	3rd floor storage room (SR) at table	08:01	10:02	121	10.00	1,210.00	0.5/100	<7.0	<0.002
193142-01-002-15-05	Post-Test	3rd floor SR at s.w. corner at door	08:49	10:52	123	9.90	1,217.70	1.0/100	<7.0	<0.002
193142-01-002-15-06	Post-Test	3rd floor Utility Room at entrance	08:50	10:53	123	9.90	1,217.70	2.5/100	<7.0	<0.002
193142-01-002-15-07	Post-Test	213 at radiator	10:30	13:03	153	8.00	1,224.00	2.0/100	<7.0	<0.002
193142-01-002-15-08	Post-Test	2nd floor Utility Room at door	10:31	13:05	154	8.00	1,232.00	2.5/100	<7.0	<0.002
193142-01-002-15-09	Field Blank	Blanl				0.00		0.0/100	<7.0	
193142-01-002-15-10	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Report Date: 1/12/2020

Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site
Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-15-01	Post-Test	314 at vat-job		1/4/2020	
193142-01-002-15-02	Post-Test	3rd floor print-room at door		1/4/2020	
193142-01-002-15-03	Post-Test	313 at radiator		1/4/2020	
193142-01-002-15-04	Post-Test	3rd floor storage room (SR) at table		1/4/2020	
193142-01-002-15-05	Post-Test	3rd floor SR at s.w. corner at door		1/4/2020	
193142-01-002-15-06	Post-Test	3rd floor Utility Room at entrance		1/4/2020	
193142-01-002-15-07	Post-Test	213 at radiator		1/4/2020	
193142-01-002-15-08	Post-Test	2nd floor Utility Room at door		1/4/2020	
193142-01-002-15-09	Field Blank	Blanl		1/4/2020	
193142-01-002-15-10	Field Blank	Blank		1/4/2020	

Sample Count \_\_10\_


Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/4/2020	15:26	
Send Reports To	School District of Philadelphia	1/4/2020	15:26	
Samples Taken By	Paul Scally	1/4/2020	15:26	
Analyzed By	P. Scally	1/4/2020	15:26	
Received By	P. Scally	1/4/2020	15:26	
Relinquished By	P. Scally	1/4/2020	15:26	
Transported By	P. Scally	1/4/2020	15:26	



Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 1/5/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 1/5/2020 Scally, Paul Collected By Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 1/5/2020

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-16-01	Post-Test	103 at cap-job	07:38	10:08	150	8.00	1,200.00	1.5/100	<7.0	< 0.002
193142-01-002-16-02	Post-Test	101 bathroom at cap-job	07:39	10:09	150	8.00	1,200.00	1.0/100	<7.0	<0.002
193142-01-002-16-03	Post-Test	Closet across from 207	10:10	12:13	123	9.90	1,217.70	0.5/100	<7.0	<0.002
193142-01-002-16-04	Post-Test	203 at cap-job	10:11	12:14	123	9.80	1,205.40	1.0/100	<7.0	<0.002
193142-01-002-16-05	Post-Test	1st floor s.w. hallway at vat-job	10:55	13:00	125	9.90	1,237.50	1.5/100	<7.0	<0.002
193142-01-002-16-06	Post-Test	1st floor Utility Room	10:56	13:01	125	9.80	1,225.00	2.0/100	<7.0	<0.002
193142-01-002-16-07	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-16-08	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count 8



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

**Container** Cassette **Project** 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

Committee Normalism	Camanda Tama	Landina	Received	Data	Matas
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-16-01	Post-Test	103 at cap-job		1/5/2020	
193142-01-002-16-02	Post-Test	101 bathroom at cap-job		1/5/2020	
193142-01-002-16-03	Post-Test	Closet across from 207		1/5/2020	
193142-01-002-16-04	Post-Test	203 at cap-job		1/5/2020	
193142-01-002-16-05	Post-Test	1st floor s.w. hallway at vat-job		1/5/2020	
193142-01-002-16-06	Post-Test	1st floor Utility Room		1/5/2020	
193142-01-002-16-07	Field Blank	Blank		1/5/2020	
193142-01-002-16-08	Field Blank	Blank		1/5/2020	

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/5/2020	15:42	
Send Reports To	School District of Philadelphia	1/5/2020	15:42	
Samples Taken By	Paul Scally	1/5/2020	15:42	
Analyzed By	P. Scally	1/5/2020	15:42	
Received By	P. Scally	1/5/2020	15:42	
Relinquished By	P. Scally	1/5/2020	15:42	
Transported By	P. Scally	1/5/2020	15:42	

Tile and




## **Results of Phase Contrast Microscopy**

Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 1/6/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 1/6/2020 Collected By Scally, Paul Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 1/6/2020

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
			Otart	•					1/111111	
193142-01-002-17-01	Post-Test	2nd floor hallway at 210	15:15	17:15	120	10.00	1,200.00	2.0/100	<7.0	<0.002
193142-01-002-17-02	Area Sample	108 at entrance	15:17	19:18	241	5.00	1,205.00	1.5/100	<7.0	<0.002
193142-01-002-17-03	Area Sample	107 at desk	15:18	19:20	242	5.00	1,210.00	2.0/100	<7.0	<0.002
193142-01-002-17-04	Area Sample	107 at entrance	17:15	19:15	120	10.00	1,200.00	1.5/100	<7.0	<0.002
193142-01-002-17-05	Area Sample	108 near closet	19:19	21:21	122	9.90	1,207.80	2.0/100	<7.0	<0.002
193142-01-002-17-06	Area Sample	107 at riser	19:20	21:25	125	9.80	1,225.00	12.5/100	15.9	0.005
193142-01-002-17-07	Area Sample	107 at entrance	19:21	21:26	125	10.00	1,250.00	1.5/100	<7.0	<0.002
193142-01-002-17-08	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-17-09	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count

9



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

**Container** Cassette **Project** 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

#### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-17-01	Post-Test	2nd floor hallway at 210		1/6/2020	
193142-01-002-17-02	Area Sample	108 at entrance		1/6/2020	
193142-01-002-17-03	Area Sample	107 at desk		1/6/2020	
193142-01-002-17-04	Area Sample	107 at entrance		1/6/2020	
193142-01-002-17-05	Area Sample	108 near closet		1/6/2020	
193142-01-002-17-06	Area Sample	107 at riser		1/6/2020	
193142-01-002-17-07	Area Sample	107 at entrance		1/6/2020	
193142-01-002-17-08	Field Blank	Blank		1/6/2020	
193142-01-002-17-09	Field Blank	Blank		1/6/2020	

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/6/2020	23:18	
Send Reports To	School District of Philadelphia	1/6/2020	23:18	
Samples Taken By	Paul Scally	1/6/2020	23:18	
Analyzed By	P. Scally	1/6/2020	23:18	
Received By	P. Scally	1/6/2020	23:18	
Relinquished By	P. Scally	1/6/2020	23:18	
Transported By	P. Scally	1/6/2020	23:18	




Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 1/7/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 1/7/2020 19111 Collected By Scally, Paul Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 1/7/2020

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-18-01	Post-Test	107 in tent at hepa inlet	11:15	13:15	120	10.00	1,200.00	1.0/100	<7.0	<0.002
193142-01-002-18-02	Post-Test	107 in tent at riser	11:16	13:17	121	10.00	1,210.00	0.5/100	<7.0	<0.002
193142-01-002-18-03	Area Sample	108 at entrance	11:30	14:52	202	6.00	1,212.00	1.5/100	<7.0	<0.002
193142-01-002-18-04	Area Sample	101 near bathroom	11:45	15:06	201	6.00	1,206.00	1.0/100	<7.0	<0.002
193142-01-002-18-05	Area Sample	314 at desk	12:20	15:40	200	6.00	1,200.00	1.0/100	<7.0	<0.002
193142-01-002-18-06	Post-Test	Custodial closet near B-1	15:20	17:22	122	10.00	1,220.00	2.0/100	<7.0	<0.002
193142-01-002-18-07	Post-Test	112 at center	15:22	17:25	123	10.00	1,230.00	0.5/100	<7.0	<0.002
193142-01-002-18-08	Post-Test	113 at window	15:30	17:30	120	10.00	1,200.00	1.0/100	<7.0	<0.002
193142-01-002-18-09	Post-Test	3rd floor staff restroom	15:40	17:43	123	9.80	1,205.40	2.0/100	<7.0	<0.002
193142-01-002-18-10	Post-Test	S.w. stairwell between 1st floor and basement	17:25	19:27	122	9.90	1,207.80	2.5/100	<7.0	<0.002
193142-01-002-18-11	Post-Test	1st floor stairwell at new wing	17:25	19:28	123	10.00	1,230.00	1.0/100	<7.0	<0.002
193142-01-002-18-12	Post-Test	Women's restroom near 107	17:28	19:29	121	10.00	1,210.00	1.0/100	<7.0	<0.002
193142-01-002-18-13	Post-Test	1st floor stairwell #1	18:15	20:17	122	10.00	1,220.00	2.0/100	<7.0	<0.002
193142-01-002-18-14	Post-Test	Basement stairwell #2	18:20	20:23	123	9.80	1,205.40	1.5/100	<7.0	<0.002
193142-01-002-18-15	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-18-16	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count

16



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Report Date: 1/12/2020

Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-18-01	Post-Test	107 in tent at hepa inlet		1/7/2020	
193142-01-002-18-02	Post-Test	107 in tent at riser		1/7/2020	
193142-01-002-18-03	Area Sample	108 at entrance		1/7/2020	
193142-01-002-18-04	Area Sample	101 near bathroom		1/7/2020	
193142-01-002-18-05	Area Sample	314 at desk		1/7/2020	
193142-01-002-18-06	Post-Test	Custodial closet near B-1		1/7/2020	
193142-01-002-18-07	Post-Test	112 at center		1/7/2020	
193142-01-002-18-08	Post-Test	113 at window		1/7/2020	
193142-01-002-18-09	Post-Test	3rd floor staff restroom		1/7/2020	
193142-01-002-18-10	Post-Test	S.w. stairwell between 1st floor and basement		1/7/2020	
193142-01-002-18-11	Post-Test	1st floor stairwell at new wing		1/7/2020	
193142-01-002-18-12	Post-Test	Women's restroom near 107		1/7/2020	
193142-01-002-18-13	Post-Test	1st floor stairwell #1		1/7/2020	
193142-01-002-18-14	Post-Test	Basement stairwell #2		1/7/2020	
193142-01-002-18-15	Field Blank	Blank		1/7/2020	
193142-01-002-18-16	Field Blank	Blank		1/7/2020	

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/7/2020	23:34	
Send Reports To	School District of Philadelphia	1/7/2020	23:34	
Samples Taken By	Paul Scally	1/7/2020	23:34	
Analyzed By	P. Scally	1/7/2020	23:34	




Received By	P. Scally	1/7/2020 23:34
Relinquished By	P. Scally	1/7/2020 23:34
Transported By	P Scally	1/7/2020 23:34



Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 1/8/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 1/8/2020 19111 Collected By Scally, Paul 1/8/2020 Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s)

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-19-01	Area Sample	Room 101 at Bathroom	11:10	14:30	200	6.00	1,200.00	1.5/100	<7.0	< 0.002
193142-01-002-19-02	Post-Test	Room 108 in tent at hepa	11:15	13:15	120	10.00	1,200.00	2.5/100	<7.0	<0.002
193142-01-002-19-03	Post-Test	Room 108 at riser	11:16	13:17	121	10.00	1,210.00	2.0/100	<7.0	<0.002
193142-01-002-19-04	Post-Test	Room 314 in tent at hepa	11:20	13:22	122	9.90	1,207.80	1.0/100	<7.0	<0.002
193142-01-002-19-05	Post-Test	Room 314 at riser	11:21	13:23	122	9.90	1,207.80	1.0/100	<7.0	<0.002
193142-01-002-19-06	Area Sample	B-7 at desk	12:00	14:35	155	8.00	1,240.00	3.5/100	<7.0	<0.002
193142-01-002-19-07	Area Sample	308 at entrance	12:30	14:32	122	9.90	1,207.80	3.0/100	<7.0	<0.002
193142-01-002-19-08	Area Sample	Stairwell 3 between 1st and 2nd floors	14:00	16:00	120	10.00	1,200.00	1.5/100	<7.0	<0.002
193142-01-002-19-09	Area Sample	101 at Bathroom closet	15:31	20:32	301	4.00	1,204.00	3.0/100	<7.0	<0.002
193142-01-002-19-10	Area Sample	308 at closet	15:33	20:34	301	4.00	1,204.00	2.0/100	<7.0	<0.002
193142-01-002-19-11	Area Sample	B-7 at closet	15:36	20:37	301	4.00	1,204.00	2.5/100	<7.0	<0.002
193142-01-002-19-12	Post-Test	200 at cap-job	17:00	21:00	240	5.00	1,200.00	1.5/100	<7.0	<0.002
193142-01-002-19-13	Post-Test	202 at risers	17:01	21:02	241	5.00	1,205.00	3.5/100	<7.0	<0.002
193142-01-002-19-14	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-19-15	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-19-16	Area Sample	B-2 at closet	19:08	21:09	121	10.00	1,210.00	3.0/100	<7.0	<0.002
193142-01-002-19-17	Area Sample	Hallway near B-2	19:09	21:11	122	9.90	1,207.80	2.0/100	<7.0	<0.002

Sample Count 17



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation From the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

**Turnaround** On-Site

Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-19-01	Area Sample	Room 101 at Bathroom		1/8/2020	
193142-01-002-19-02	Post-Test	Room 108 in tent at hepa		1/8/2020	
193142-01-002-19-03	Post-Test	Room 108 at riser		1/8/2020	
193142-01-002-19-04	Post-Test	Room 314 in tent at hepa		1/8/2020	
193142-01-002-19-05	Post-Test	Room 314 at riser		1/8/2020	
193142-01-002-19-06	Area Sample	B-7 at desk		1/8/2020	
193142-01-002-19-07	Area Sample	308 at entrance		1/8/2020	
193142-01-002-19-08	Area Sample	Stairwell 3 between 1st and 2nd floors		1/8/2020	
193142-01-002-19-09	Area Sample	101 at Bathroom closet		1/8/2020	
193142-01-002-19-10	Area Sample	308 at closet		1/8/2020	
193142-01-002-19-11	Area Sample	B-7 at closet		1/8/2020	
193142-01-002-19-12	Post-Test	200 at cap-job		1/8/2020	
193142-01-002-19-13	Post-Test	202 at risers		1/8/2020	
193142-01-002-19-14	Field Blank	Blank		1/8/2020	
193142-01-002-19-15	Field Blank	Blank		1/8/2020	
193142-01-002-19-16	Area Sample	B-2 at closet		1/8/2020	
193142-01-002-19-17	Area Sample	Hallway near B-2		1/8/2020	

Sample Count \_\_17\_

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/8/2020	23:13	
Send Reports To	School District of Philadelphia	1/8/2020	23:13	
Samples Taken By	Paul Scally	1/8/2020	23:13	
Analyzed By	P. Scally	1/8/2020	23:13	
Received By	P. Scally	1/8/2020	23:13	
Relinquished By	P. Scally	1/8/2020	23:13	



Transported By

P. Scally

1/8/2020

23:13



Report Date: 1/12/2020

### Results of Phase Contrast Microscopy

School District of Philadelphia Carnell Elementary School - 1100 Sample Date Client Site Address 1/9/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 1/11/2020 19111 Collected By Criterion Laboratories, Inc. Analyzed By Oseroff, Samuel Sample Analysis Date(s) 1/9/2020

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-20-01	Post-Test	308 closet in tent	11:26	13:30	124	9.96	1,235.04	10.0/100	12.7	0.004
193142-01-002-20-02	Post-Test	308 closet in tent	11:26	13:31	125	9.96	1,245.00	8.5/100	10.8	0.003
193142-01-002-20-03	Post-Test	B7/007 middle closet in Tent	12:02	14:06	124	9.96	1,235.04	8.0/100	10.2	0.003
193142-01-002-20-04	Post-Test	B7/007 middle closet in tent	12:03	14:06	123	9.96	1,225.08	6.5/100	8.3	0.003
193142-01-002-20-05	Post-Test	101 bathroom in tent	13:41	15:45	124	9.96	1,235.04	14.0/100	17.8	0.006
193142-01-002-20-06	Post-Test	101 bathroom in tent	13:42	15:45	123	9.96	1,225.08	8.5/100	10.8	0.003
193142-01-002-20-07	Post-Test	Basement custodial closet jc0	14:11	16:14	123	9.96	1,225.08	4.5/100	<7.0	< 0.002
193142-01-002-20-08	Post-Test	Basement custodial closet jc0	14:11	16:14	123	9.96	1,225.08	6.5/100	8.3	0.003
193142-01-002-20-09	Post-Test	308 closet in tent	15:22	17:26	124	9.96	1,235.04	5.0/100	<7.0	< 0.002
193142-01-002-20-10	Post-Test	308 closet in tent	15:22	17:27	125	9.96	1,245.00	3.5/100	<7.0	< 0.002
193142-01-002-20-11	Post-Test	308 closet in tent	15:22	17:27	125	9.96	1,245.00	4.0/100	<7.0	< 0.002
193142-01-002-20-12	Post-Test	B7/007 middle closet in Tent	15:28	17:35	127	9.96	1,264.92	15.0/100	19.1	0.006
193142-01-002-20-13	Post-Test	B7/007 middle closet in Tent	15:29	17:35	126	9.96	1,254.96	18.0/100	22.9	0.007
193142-01-002-20-14	Post-Test	B7/007 middle closet in Tent	15:29	17:35	126	9.96	1,254.96	12.5/100	15.9	0.005
193142-01-002-20-15	Post-Test	101 bathroom in tent	15:46	17:53	127	9.96	1,264.92	4.0/100	<7.0	< 0.002
193142-01-002-20-16	Post-Test	101 bathroom in tent	15:46	17:53	127	9.96	1,264.92	6.0/100	7.6	0.002
193142-01-002-20-17	Post-Test	101 bathroom in tent	15:46	17:53	127	9.96	1,264.92	7.5/100	9.6	0.003
193142-01-002-20-18	Post-Test	Hallway outside b7	15:50	18:10	140	9.96	1,394.40	6.5/100	8.3	0.002
193142-01-002-20-19	Post-Test	107 in tent	17:59	20:06	127	9.96	1,264.92	2.0/100	<7.0	< 0.002
193142-01-002-20-20	Post-Test	107 in tent	18:00	20:06	126	9.96	1,254.96	3.0/100	<7.0	< 0.002
193142-01-002-20-21	Post-Test	107 in tent	18:00	20:06	126	9.96	1,254.96	3.0/100	<7.0	< 0.002
193142-01-002-20-22	Post-Test	108 closet in tent	17:43	20:00	137	9.96	1,364.52	4.5/100	<7.0	< 0.002
193142-01-002-20-23	Post-Test	108 closet in tent	17:43	20:00	137	9.96	1,364.52	4.0/100	<7.0	< 0.002
193142-01-002-20-24	Post-Test	108 closet in tent	17:43	20:00	137	9.96	1,364.52	6.0/100	7.6	0.002
193142-01-002-20-25	Post-Test	B7 closet by door	17:38	19:46	128	9.96	1,274.88	4.5/100	<7.0	< 0.002
193142-01-002-20-26	Post-Test	B7 closet by door	17:38	19:46	128	9.96	1,274.88	2.5/100	<7.0	< 0.002
193142-01-002-20-27	Post-Test	314 in tent	17:30	19:40	130	9.96	1,294.80	4.0/100	<7.0	< 0.002
193142-01-002-20-28	Post-Test	314 in tent	17:30	19:40	130	9.96	1,294.80	7.0/100	8.9	0.003
193142-01-002-20-29	Post-Test	314 in tent	17:31	19:40	129	9.96	1,284.84	5.5/100	7.0	0.002
193142-01-002-20-30	Post-Test	B7 (repairs)	20:13	22:25	132	9.96	1,314.72	5.0/100	<7.0	<0.002
193142-01-002-20-31	Post-Test	Basement staff restroom (repairs)	20:16	22:29	133	9.96	1,324.68	2.0/100	<7.0	<0.002
193142-01-002-20-32	Post-Test	Art room closet (repairs)	20:20	22:32	132	9.96	1,314.72	3.5/100	<7.0	< 0.002
193142-01-002-20-33	Post-Test	Basement gas meter closet (repairs)	20:25	22:34	129	9.96	1,284.84	3.0/100	<7.0	<0.002



Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 1/9/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 1/11/2020 Oseroff, Samuel Collected By Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 1/9/2020

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-20-34	Post-Test	Stairwell 1 between basement and 1st floor (repair)	20:29	22:37	128	9.96	1,274.88	5.0/100	<7.0	<0.002
193142-01-002-20-35	Post-Test	IMC by smart board (VAT)	20:36	22:40	124	9.96	1,235.04	5.0/100	<7.0	<0.002
193142-01-002-20-36	Post-Test	IMC by office (VAT)	20:38	22:40	122	9.96	1,215.12	4.5/100	<7.0	<0.002
193142-01-002-20-37	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-20-38	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-20-39	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-20-40	Field Blank	Blank						0.0/100	<7.0	

Sample Count

g-caeg-

James A. Weltz, CIH, Technical Director

Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Report Date: 1/12/2020

Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

**Analyte** Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Sam Oseroff

**Sample Notes** 

**Chain of Custody** 

**Notes** 

### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-20-01	Post-Test	308 closet in tent		1/10/2020	
193142-01-002-20-02	Post-Test	308 closet in tent		1/10/2020	
193142-01-002-20-03	Post-Test	B7/007 middle closet in Tent		1/10/2020	
193142-01-002-20-04	Post-Test	B7/007 middle closet in tent		1/10/2020	
193142-01-002-20-05	Post-Test	101 bathroom in tent		1/10/2020	
193142-01-002-20-06	Post-Test	101 bathroom in tent		1/10/2020	
193142-01-002-20-07	Post-Test	Basement custodial closet jc0		1/10/2020	
193142-01-002-20-08	Post-Test	Basement custodial closet jc0		1/10/2020	
193142-01-002-20-09	Post-Test	308 closet in tent		1/10/2020	
193142-01-002-20-10	Post-Test	308 closet in tent		1/10/2020	
193142-01-002-20-11	Post-Test	308 closet in tent		1/10/2020	
193142-01-002-20-12	Post-Test	B7/007 middle closet in Tent		1/10/2020	
193142-01-002-20-13	Post-Test	B7/007 middle closet in Tent		1/10/2020	
193142-01-002-20-14	Post-Test	B7/007 middle closet in Tent		1/10/2020	
193142-01-002-20-15	Post-Test	101 bathroom in tent		1/10/2020	
193142-01-002-20-16	Post-Test	101 bathroom in tent		1/10/2020	
193142-01-002-20-17	Post-Test	101 bathroom in tent		1/10/2020	
193142-01-002-20-18	Post-Test	Hallway outside b7		1/10/2020	
193142-01-002-20-19	Post-Test	107 in tent		1/10/2020	
193142-01-002-20-20	Post-Test	107 in tent		1/10/2020	
193142-01-002-20-21	Post-Test	107 in tent		1/10/2020	
193142-01-002-20-22	Post-Test	108 closet in tent		1/10/2020	
193142-01-002-20-23	Post-Test	108 closet in tent		1/10/2020	
193142-01-002-20-24	Post-Test	108 closet in tent		1/10/2020	
193142-01-002-20-25	Post-Test	B7 closet by door		1/10/2020	
193142-01-002-20-26	Post-Test	B7 closet by door		1/10/2020	



193142-01-002-20-27	Post-Test	314 in tent	1/10/2020
193142-01-002-20-28	Post-Test	314 in tent	1/10/2020
193142-01-002-20-29	Post-Test	314 in tent	1/10/2020
193142-01-002-20-30	Post-Test	B7 (repairs)	1/10/2020
193142-01-002-20-31	Post-Test	Basement staff restroom (repairs)	1/10/2020
193142-01-002-20-32	Post-Test	Art room closet (repairs)	1/10/2020
193142-01-002-20-33	Post-Test	Basement gas meter closet (repairs)	1/10/2020
193142-01-002-20-34	Post-Test	Stairwell 1 between basement and 1st floor (repair)	1/10/2020
193142-01-002-20-35	Post-Test	IMC by smart board (VAT)	1/10/2020
193142-01-002-20-36	Post-Test	IMC by office (VAT)	1/10/2020
193142-01-002-20-37	Field Blank	Blank	1/10/2020
193142-01-002-20-38	Field Blank	Blank	1/10/2020
193142-01-002-20-39	Field Blank	Blank	1/10/2020
193142-01-002-20-40	Field Blank	Blank	1/10/2020

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/10/2020	20:24	
Send Reports To	School District of Philadelphia	1/10/2020	20:24	
Samples Taken By	Sam Oseroff	1/10/2020	20:24	
Received By	Sam Oseroff	1/11/2020	00:00	
Relinquished By	Sam Oseroff	1/11/2020	00:00	
Analyzed By	Sam Oseroff	1/11/2020	00:00	

Tile e e




### Results of Phase Contrast Microscopy

Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 1/9/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 1/9/2020 Sample Received Date Scally, Paul 1/9/2020 Collected By Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s)

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-21-01	Post-Test	Room 303 at entrance	16:10	18:10	120	10.00	1,200.00	4.5/100	<7.0	<0.002
193142-01-002-21-02	Post-Test	Room 311 at center	16:15	18:18	123	9.80	1,205.40	5.0/100	<7.0	<0.002
193142-01-002-21-03	Post-Test	Room 302 at door	16:20	19:00	160	8.00	1,280.00	3.0/100	<7.0	<0.002
193142-01-002-21-04	Post-Test	1st floor s.e. storage room	17:09	19:09	120	10.00	1,200.00	11.0/100	14.0	0.005
193142-01-002-21-05	Post-Test	Room 211 at center	17:28	19:29	121	10.00	1,210.00	4.0/100	<7.0	<0.002
193142-01-002-21-06	Post-Test	3rd floor s.w. hallway at riser	19:50	21:52	122	9.90	1,207.80	2.0/100	<7.0	<0.002
193142-01-002-21-07	Post-Test	Staff Men's restroom at door	19:53	21:53	120	10.00	1,200.00	2.5/100	<7.0	<0.002
193142-01-002-21-08	Post-Test	Room 313 at desk	19:52	21:54	122	9.90	1,207.80	2.5/100	<7.0	<0.002
193142-01-002-21-09	Post-Test	Room 201 at center	19:55	21:55	120	10.00	1,200.00	2.0/100	<7.0	<0.002
193142-01-002-21-10	Post-Test	Room at entrance	19:58	22:00	122	10.00	1,220.00	2.0/100	<7.0	<0.002
193142-01-002-21-11	Field Blank	Blank				0.00		0.0/100	<7.0	
193142-01-002-21-12	Field Blank	Blank				0.00		0.0/100	<7.0	

Sample Count

\_12\_



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Report Date: 1/12/2020

Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



**Matrix** Air

Analyte Asbestos

Analysis Type PCM

**Container** Cassette **Project** 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Paul Scally

**Sample Notes** 

**Chain of Custody** 

**Notes** 

### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-21-01	Post-Test	Room 303 at entrance		1/9/2020	
193142-01-002-21-02	Post-Test	Room 311 at center		1/9/2020	
193142-01-002-21-03	Post-Test	Room 302 at door		1/9/2020	
193142-01-002-21-04	Post-Test	1st floor s.e. storage room		1/9/2020	
193142-01-002-21-05	Post-Test	Room 211 at center		1/9/2020	
193142-01-002-21-06	Post-Test	3rd floor s.w. hallway at riser		1/9/2020	
193142-01-002-21-07	Post-Test	Staff Men's restroom at door		1/9/2020	
193142-01-002-21-08	Post-Test	Room 313 at desk		1/9/2020	
193142-01-002-21-09	Post-Test	Room 201 at center		1/9/2020	
193142-01-002-21-10	Post-Test	Room at entrance		1/9/2020	
193142-01-002-21-11	Field Blank	Blank		1/9/2020	
193142-01-002-21-12	Field Blank	Blank		1/9/2020	

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/9/2020	23:25	
Send Reports To	School District of Philadelphia	1/9/2020	23:25	
Samples Taken By	Paul Scally	1/9/2020	23:25	
Analyzed By	P. Scally	1/9/2020	23:25	
Received By	P. Scally	1/9/2020	23:25	
Relinquished By	P. Scally	1/9/2020	23:25	
Transported By	P. Scally	1/9/2020	23:25	




Client School District of Philadelphia Site Address Carnell Elementary School - 1100 Sample Date 1/10/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 1/11/2020 Collected By Oseroff, Samuel Criterion Laboratories, Inc. Analyzed By Sample Analysis Date(s) 1/10/2020

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-22-01	Post-Test	Student lunch room (vat)	09:30	11:47	137	9.89	1,354.93	3.0/100	<7.0	<0.002
193142-01-002-22-02	Post-Test	Student lunch room	09:31	11:47	136	9.89	1,345.04	5.5/100	7.0	0.002
193142-01-002-22-03	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-22-04	Field Blank	Blank						0.0/100	<7.0	

Sample Count





James A. Weltz, CIH, Technical Director

Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits: Samples were received in good condition, \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Report Date: 1/12/2020

Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

**Container** Cassette **Project** 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Sam Oseroff

**Sample Notes** 

**Chain of Custody** 

**Notes** 

### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-22-01	Post-Test	Student lunch room (vat)		1/10/2020	
193142-01-002-22-02	Post-Test	Student lunch room		1/10/2020	
193142-01-002-22-03	Field Blank	Blank		1/10/2020	
193142-01-002-22-04	Field Blank	Blank		1/10/2020	

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/10/2020	20:21	
Send Reports To	School District of Philadelphia	1/10/2020	20:21	
Samples Taken By	Sam Oseroff	1/10/2020	20:21	
Analyzed By	Sam Oseroff	1/11/2020	00:00	
Received By	Sam Oseroff	1/11/2020	00:00	
Relinquished By	Sam Oseroff	1/11/2020	00:00	




School District of Philadelphia Carnell Elementary School - 1100 Sample Date Client Site Address 1/10/2020 Devereaux Avenue, Philadelphia, PA Project # 193142 Sample Received Date 1/11/2020 19111 Collected By Criterion Laboratories, Inc. Analyzed By Oseroff, Samuel Sample Analysis Date(s) 1/10/2020

Sample Number	Sample Type	Location	Start	Stop	Mins	Flow Rate (LPM)	Volume (L)	Fibers /Fields	Fiber Density f/mm²	Fiber /cc
193142-01-002-23-01	Area Sample	Classroom 103 - Center of W3	11:33	13:40	127	9.96	1,264.92	3.5/100	<7.0	<0.002
193142-01-002-23-02	Area Sample	Classroom B1 - Outside Work Area (OWA) - Viewport	07:39	11:08	209	5.87	1,226.83	7.0/100	8.9	0.003
193142-01-002-23-03	Area Sample	Classroom B1 - Inside Work Area (IWA) - Left of Trap	07:42	11:10	208	5.87	1,220.96	9.0/100	11.5	0.004
193142-01-002-23-04	Post-Test	Classroom 105 - Center of W3	12:47	15:00	133	9.96	1,324.68	5.0/100	<7.0	<0.002
193142-01-002-23-05	Area Sample	2nd Floor Hallway - Outside Classroom 211	13:05	15:09	124	9.96	1,235.04	6.5/100	8.3	0.003
193142-01-002-23-06	Area Sample	2nd Floor Hallway - Outside Classroom 2112	13:07	15:10	123	9.96	1,225.08	4.0/100	<7.0	<0.002
193142-01-002-23-07	Post-Test	Classroom 103 - Center of W3	13:41	15:58	137	9.96	1,364.52	6.0/100	7.6	0.002
193142-01-002-23-08	Post-Test	Classroom 212 - Right Side of W3	16:13	18:20	127	9.96	1,264.92	7.0/100	8.9	0.003
193142-01-002-23-09	Post-Test	Classroom 213 - Right Side of W3	16:16	18:22	126	9.96	1,254.96	3.0/100	<7.0	<0.002
193142-01-002-23-10	Post-Test	2nd Floor Storage Room by New Wing	16:34	18:40	126	9.96	1,254.96	2.0/100	<7.0	<0.002
193142-01-002-23-11	Post-Test	Nurse's Office	17:47	19:50	123	9.96	1,225.08	3.5/100	<7.0	<0.002
193142-01-002-23-12	Area Sample	Classroom B1 - OWA - Viewport	11:10	14:55	225	5.87	1,320.75	8.0/100	10.2	0.003
193142-01-002-23-13	Area Sample	Classroom B1 - IWA - Left of Trap	11:11	14:56	225	5.87	1,320.75	10.0/100	12.7	0.004
193142-01-002-23-14	Post-Test	Classroom 110 -	19:19	21:34	135	9.96	1,344.60	5.0/100	<7.0	<0.002
193142-01-002-23-15	Post-Test	Classroom 111 -	19:22	21:30	128	9.96	1,274.88	5.5/100	7.0	0.002
193142-01-002-23-16	Post-Test	1st Floor - Counselors Office	19:16	21:26	130	9.96	1,294.80	6.0/100	7.6	0.002
193142-01-002-23-17	Area Sample	Classroom B1 - OWA - Viewport	14:55	18:00	185	9.96	1,842.60	8.0/100	10.2	0.002
193142-01-002-23-18	Area Sample	Classroom B1 - IWA - Left of Trap	14:57	18:00	183	9.96	1,822.68	22.5/100	28.7	0.006
193142-01-002-23-19	Post-Test	101 closet (vat)	19:51	21:58	127	9.96	1,264.92	5.0/100	<7.0	<0.002
193142-01-002-23-20	Post-Test	101 closet	19:52	21:58	126	9.96	1,254.96	6.0/100	7.6	0.002
193142-01-002-23-21	Post-Test	Assistant principal office	20:02	22:06	124	9.96	1,235.04	2.0/100	<7.0	<0.002
193142-01-002-23-22	Post-Test	Nurses office	20:05	22:14	129	9.96	1,284.84	4.5/100	<7.0	<0.002
193142-01-002-23-23	Post-Test	3rd floor Hall by 314	20:10	23:01	171	9.96	1,703.16	6.0/100	7.6	0.002
193142-01-002-23-24	Field Blank	Blank						0.0/100	<7.0	
193142-01-002-23-25	Field Blank	Blank						0.0/100	<7.0	

Sample Count <u>25</u>



Client	School District of Philadelphia	Site Address	Carnell Elementary School - 1100	Sample Date	1/10/2020
Project #	193142		Devereaux Avenue, Philadelphia, PA 19111	Sample Received Date	1/11/2020
Collected By	Criterion Laboratories, Inc.	Analyzed By	Oseroff, Samuel	Sample Analysis Date(s)	1/10/2020



Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. This report relates only to the samples reported above, and when reproduced, must be in its entirety. Blank results are subtracted from any results; QC data associated with this sample set is within acceptable limits; Samples were received in good condition. \*\* Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using Phase Contrast Microscopy, Method CLI 11 (NIOSH Method 7400M).



Report Date: 1/12/2020

Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.



Matrix Air

Analyte Asbestos

Analysis Type PCM

Container Cassette
Project 193142

Client School District of Philadelphia

Site Address Carnell Elementary School - 1100 Devereaux Avenue,

Philadelphia, PA 19111

Turnaround On-Site

Field Tech Sam Oseroff

**Sample Notes** 

**Chain of Custody** 

**Notes** 

### **Additional Analytes**

			Received		
Sample Number	Sample Type	Location	Condition	Date	Notes
193142-01-002-23-01	Area Sample	Classroom 103 - Center of W3		1/10/2020	
193142-01-002-23-02	Area Sample	Classroom B1 - Outside Work Area (OWA) - Viewport		1/10/2020	
193142-01-002-23-03	Area Sample	Classroom B1 - Inside Work Area (IWA) - Left of Trap		1/10/2020	
193142-01-002-23-04	Post-Test	Classroom 105 - Center of W3		1/10/2020	
193142-01-002-23-05	Area Sample	2nd Floor Hallway - Outside Classroom 211		1/10/2020	
193142-01-002-23-06	Area Sample	2nd Floor Hallway - Outside Classroom 2112		1/10/2020	
193142-01-002-23-07	Post-Test	Classroom 103 - Center of W3		1/10/2020	
193142-01-002-23-08	Post-Test	Classroom 212 - Right Side of W3		1/10/2020	
193142-01-002-23-09	Post-Test	Classroom 213 - Right Side of W3		1/10/2020	
193142-01-002-23-10	Post-Test	2nd Floor Storage Room by New Wing		1/10/2020	
193142-01-002-23-11	Post-Test	Nurse's Office		1/10/2020	
193142-01-002-23-12	Area Sample	Classroom B1 - OWA - Viewport		1/10/2020	
193142-01-002-23-13	Area Sample	Classroom B1 - IWA - Left of Trap		1/10/2020	
193142-01-002-23-14	Post-Test	Classroom 110 -		1/10/2020	
193142-01-002-23-15	Post-Test	Classroom 111 -		1/10/2020	
193142-01-002-23-16	Post-Test	1st Floor - Counselors Office		1/10/2020	



193142-01-002-23-17	Area Sample	Classroom B1 - OWA - Viewport	1/10/2020
193142-01-002-23-18	Area Sample	Classroom B1 - IWA - Left of Trap	1/10/2020
193142-01-002-23-19	Post-Test	101 closet (vat)	1/10/2020
193142-01-002-23-20	Post-Test	101 closet	1/10/2020
193142-01-002-23-21	Post-Test	Assistant principal office	1/10/2020
193142-01-002-23-22	Post-Test	Nurses office	1/10/2020
193142-01-002-23-23	Post-Test	3rd floor Hall by 314	1/10/2020
193142-01-002-23-24	Field Blank	Blank	1/10/2020
193142-01-002-23-25	Field Blank	Blank	1/10/2020

Handling Chain Type	Handled By	Date	Time	Notes
Report Results To	lan Forster	1/10/2020	23:19	
Send Reports To	School District of Philadelphia	1/10/2020	23:19	
Samples Taken By	Sam Oseroff	1/10/2020	23:19	
Received By	Sam Oseroff	1/11/2020	00:00	
Relinquished By	Sam Oseroff	1/11/2020	00:00	
Analyzed By	Sam Oseroff	1/11/2020	00:00	